ABSTRACT

A method and device to repair fuel assembly structural defects in the top nozzle to guide thimble connection. The device includes a shaft with tendons configured to defect to allow a structural connection between a dimple and a dimple area of a guide thimble.

NY01 635881 v 1

11